


## 50PG20 INTERCONNECT DIAGRAM



During SMPS Test (Described below), P803 disconnected;

- 1) P801 and P802 connected. Y-SUS and Z-SUS will produce sustain waveforms.
- 2) P801 connected P802 disconnected, Y-SUS will produce sustain waveform, Z-SUS does not.
- 3) P801 disconnected P802 connected. No SUS waveforms are produced due to a loss of control PWB B+ routed through the Y-SUS PWB.

